

Sensor monitor with individual alarm set points converted to N2K and displayed on monitor and/or MFD and broadcast over Wifi. Alarms and MFD controlled from I pad device if desired. Sensors can be calibrated to read pressures, temperatures etc.. Lap top can be plugged in via USB for set and to act as a recorder or additional monitor. Gauge layout changed with green/yellow/ red sectors and required span. Wifi unit won't be required if MFD is wifi capable.

